

AGENDA

Four Corners Air Quality Task Force Meeting
Power Plants Work Group Agenda
Wednesday, May 9, 2007
3:00 – 5:15 pm

Time	Agenda Item
3:00 – 3:15 pm	Welcome & Introductions Quick round robin and pass sign-in sheet around
3:15 – 3:30 pm	Questions and Comments Open Work Group for Questions and Comments. Brief update on Desert Rock Energy Project, Four Corners Power Plant FIP, & other Power Plant news
3:30 – 4:00 pm	Presentation Colorado, New Mexico, & EPA 9 Clean Air Mercury Rule Summary. Mark McMillian, CDPHE Mark Jones, NMED Wilson Laughter, NNEPA
4:00 – 4:30 pm	Review Final Review of all draft mitigation options Review the Documents for completeness and accuracy. Record changes.
4:30 – 5:00 pm	Work Plan Finalization Discuss what to do about any outstanding papers. Establish deadlines in keeping with Timeline handout.
5:00 – 5:15 pm	Recap of action items and next steps Summarize action items and set agenda for conference calls Discuss who will present for work groups at final TF Meeting (Nov 7, 2007) & handout work group presentation outlines
5:15 pm	Return to Plenary Work Group Coordinators give a report back on highlights of the session

Power Plants

Work Group Coordinator: Mark Jones (NMED); Note taker: Susan Johnson (NPS)
Room: Florida